	eza ute prev	1988 I = 1 - 1 - 2000 100 100 100 100 100 100 100 100 10			AVG. 9-68	
5-43		Approved For Release 2000/08/2	ALSSALE-RUP/TI	500263R009]{() / () /	7-6
DATE	አ	<u> </u>	2	TAITEL	10 /	and the state of t
		Section and control and contro	4	COMMO	12	
er average er filler frækt og	د که در داد و داد در محمد با به رود و در خوبهای بیشتر رود. داد که استان که استان که در در محمد بازد در محمد بازد در در در محمد بازد در د		5	nuos	113	
TO			7	- RSA	15	
FROM	:			ANIA	ITV	
ACTK	יאכ			PKIUN		
INFO	:		<u> </u>		16.22	The second description of the second
				**************************************	10	
IN	94935	os	A 1-20 BJ	an and a second a second and a second a second and a second a second and a second a second a second a second and a second a second a second a second a second a second a secon		ACTION AND AND AND AND AND AND AND AND AND AN
=== 10		INFO	And the second sec	CITE	nggay - State phases, agaptigith historiae Editoriae	
۔	D O N E	T 170801Z CITE 6550				25X1A6c
po	IORITY	A2012 PRIORITY			25X1A6c	25X1A6c
	•	LOGS COMMO	TEST		20/(1/(00	25X1A2g
10	EALIST	AINING MISSION HT-67-320 FL	•	E INDICATE	NORMAL	9
						25X1A2g
Of	PER AT ION	OF THE EQUIPMENT.	TEN MINUTE	DURALION M.		25X1D0b
						25X1D0b
	2. NA	AV COMPUTER SHOWED SATISFACT	TORY PERFORMA	NCE. ONE	FLIGHT	i.
L	INE OF	180 MILES SHOWED ZERO ERROR	. MAX ERROR	ON ANY FLI	GHT	
		3 MILES, WHICH SHOWED ONCE				: : :
		ABOUT 1-1/2 MILES.				
н		OPPLER OPERATION WAS MARGIN	AL WITH INTER	MITTENT OP	ERATION	

- 3. DOPPLER OPERATION WAS MARGINAL WITH INTERMITTENT OPERATION REGARDLESS OF ALTITUDE OR LAND/SEA CONDITIONS. DRIVER COMMENTS INDICATE THAT WHEN IT DID WORK, THE PRODUCT WAS SATISFACTORY.
- G B G R E T TOR: 170848Z AUG 67